SOFTWARE RELEASE NOTES

Product: HyperWare-II, Build 2067

Release Date: 8-15-2019

FIRMWARE COMPATIBITLITY:

This build is compatible with IntelliLogger firmware versions containing '25' as the second digit in the firmware version number.

Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.

BUILD SUB-COMPONENTS AND VERSIONS:

This HyperWare-II Release contains the following sub-components. Not all components are updated in each release. For reference, the version numbers of these components are provided below:

Code Component	Version	Updated?
HyperWare.exe	1.25.1.22	Updated
MultiCommLib.dll	1.25.1.2	Not Updated
ILControls.dll	1.23.1.4	Not Updated
Clib.dll	1.23.1.2	Not Updated

MODIFICATIONS CONTAINED IN THIS RELEASE:

-Fixed a problem where the CPU Analog Input Icon's Icon Name could not be changed.