



LOGIC BEACH, Inc.

Instruments designed with the User in mind

SOFTWARE RELEASE NOTES

Product: HyperWare-II, Build 2055

Release Date: 11-10-2010

FIRMWARE COMPATIBILITY:

This build is compatible with IntelliLogger firmware versions containing '19' as the second digit in the firmware version number.

Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.

BUILD SUB-COMPONENTS AND VERSIONS:

This HyperWare-II Release contains the following sub-components. Not all components are updated in each release. For reference, the version numbers of these components are provided below:

Code Component	Version	Updated?
HyperWare.exe	1.19.1.30	Not Updated
GreenWater.exe	1.19.1.20	Updated
MultiCommLib.dll	1.19.1.10	Not Updated
ILControls.dll	1.19.1.16	Updated
Clib.dll	1.19.1.10	Not Updated

MODIFICATIONS CONTAINED IN THIS RELEASE:

Fixed a bug where Greenwater wouldn't always navigate properly to built-in web pages that were not using port 80.

Added code to explicitly stop logger from streaming data when closing GreenWater.

Added code to maximize application window upon startup.

LOGIC BEACH INCORPORATED

8363 - 6F Center Drive La Mesa, CA 91942 | Tel: 619-698-3300 | Fax: 619-469-8604 | www.logicbeach.com



LOGIC BEACH, Inc.

Instruments designed with the User in mind

Fixed problem where upon loading a custom web page where controls didn't always start updating properly.

Fixed problem where some controls would move slightly or shrink from within the Web Page Icon or Real-Time Trending design views.

LOGIC BEACH INCORPORATED

8363 - 6F Center Drive La Mesa, CA 91942 | Tel: 619-698-3300 | Fax: 619-469-8604 | www.logicbeach.com