



# LOGIC BEACH, Inc.

*Instruments designed with the User in mind*

## SOFTWARE RELEASE NOTES

**Product:** IntelliLogger Firmware, Version 1.17.3.15

**Release Date:** 3-12-2009

### FIRMWARE COMPATIBILITY:

This firmware release is compatible with HyperWare-II versions containing '**17**' as the second digit in the HyperWare-II version number.

*Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.*

### MODIFICATIONS CONTAINED IN THIS CODE SET:

A "passthrough" failure message was added to increase the clarity of Modbus error messages.

A check is now done when receiving updates to Modbus settings from the *Logger Configuration* dialog to ensure that the Modbus message timeout value is not set to zero, as this would cause the logger to hang. The logger will now automatically change a 0 to a 1.

**LOGIC BEACH INCORPORATED**

8363 - 6F Center Drive La Mesa, CA 91942

Tel: 619-698-3300

Fax: 619-469-8604

[www.logicbeach.com](http://www.logicbeach.com)