

SOFTWARE RELEASE NOTES

Product: IntelliLogger Firmware, Version 1.19.3.2

Release Date: April 29, 2011

FIRMWARE COMPATIBILITY:

This firmware release is compatible with HyperWare-II versions containing '19' as the second digit in the HyperWare-II version number.

Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.

MODIFICATIONS CONTAINED IN THIS CODE SET:

- Fixed a problem where the logger couldn't connect to the Microsoft ftp server
- Bogus value were being reported when Freq. went to zero. Added slider to Engine Freq icons.
- Added connection resource counting message
- Add a timeout to the connected mail socket. This intended to eliminate the lockup which debug traces appear to show happening after the socket is connected.
- Fixed problem that could cause open socket not to be closed properly
- Fixed a CMX bug in handling multiple-IP message command responses when sending email.
- Made mods to ensure no watchdog timeouts in low-power mode.
- Bump (c) to 2011.
- Add IL model IL-90.

LOGIC BEACH INCORPORATED

8363 - 6F Center Drive, La Mesa, CA 91942 | Tel: 619-698-3300 | Fax: 619-469-8604 | www.logicbeach.com



-Predicate updating ILIM-2 counter inputs on having the current value differ from the one previously calculated.

-Added support for Fred's Java test app.

-RTT wasn't always stopped on the logger when HW disconnected incorrectly.

LOGIC BEACH INCORPORATED

8363 - 6F Center Drive, La Mesa, CA 91942 ■ Tel: 619-698-3300 ■ Fax: 619-469-8604 ■ www.logicbeach.com