



# LOGIC BEACH, Inc.

*Instruments designed with the User in mind*

## SOFTWARE RELEASE NOTES

**Product:** HyperWare-II, Pre-Release (Beta) Ver 1.25.1.27

**Release Date:** 2-8-2021

### RELEASE SPECIFIC NOTES:

This is a Pre-Release version that has not been 100% tested. Pre-Release versions are provided in advance for customers needing new features or bug fixes. Please report any suspect or abnormal operation to Logic Beach Technical staff to assist in release testing! Thank you.

### FIRMWARE COMPATIBILITY:

This build is compatible with IntelliLogger firmware versions containing '25' as the second digit in the firmware version number.

*Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.*

### BUILD SUB-COMPONENTS AND VERSIONS:

This HyperWare-II Release contains the following sub-components. Not all components are updated in each release. For reference, the version numbers of these components are provided below:

Code Component	Version	Updated?
HyperWare.exe	1.25.1.27	Updated
MultiCommLib.dll	1.25.1.6	Updated
ILControls.dll	1.23.1.5	Updated
Clib.dll	1.23.1.3	Updated

### MODIFICATIONS CONTAINED IN THIS RELEASE:

- Added communication via Ethernet cable directly between PC and IntelliLogger (had been disabled after Ver 1.25.1.24)
- Corrected bug with Modbus Configuration tab in the Logger Configuration dialog where some Modbus settings would not persist with upload to IntelliLogger and follow-on download.

**LOGIC BEACH INCORPORATED**

8363 - 6F Center Drive La Mesa, CA 91942 | Tel: 619-698-3300 | Fax: 619-469-8604 |

www.logicbeach.com

HyperWare-II\_Beta Ver 1.25.1.27\_ReleaseNotes.pdf