



**LOGIC BEACH, Inc.**

*Instruments designed with the User in mind*

## SOFTWARE RELEASE NOTES

**Product:** IntelliLogger Firmware, Version 1.17.3.21

**Release Date:** 5-1-2009

### FIRMWARE COMPATIBILITY:

This firmware release is compatible with HyperWare-II versions containing '**17**' as the second digit in the HyperWare-II version number.

*Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.*

### MODIFICATIONS CONTAINED IN THIS CODE SET:

FTP tasks were modified to make FTP communications more robust in recovering from multiple failed connections so that the logger would not require a reset to resume communications.

All use of TCP port 1024 was removed to improve communications over Verizon Wireless networks. Under certain conditions, Verizon will block this port and cause odd miscommunication.

Corrected a bug introduced in version 1.17.3.5 that inadvertently disabled the Active FTP mode.

**LOGIC BEACH INCORPORATED**

8363 · 6F Center Drive La Mesa, CA 91942

Tel: 619-698-3300

Fax: 619-469-8604

[www.logicbeach.com](http://www.logicbeach.com)