

SOFTWARE RELEASE NOTES

Product: IntelliLogger Firmware, Version 1.21.2.6

Release Date: May 18, 2012

FIRMWARE COMPATIBITLITY:

This firmware release is compatible with HyperWare-II versions containing '21' as the second digit in the HyperWare-II version number.

Note: It is always recommended to update IntelliLogger firmware and HyperWare-II to the latest version if possible.

MODIFICATIONS CONTAINED IN THIS CODE SET:

- -Added support for IL-Mini
- -Add "MemFull: Cant ENABLE" message if ENABLE button is pressed when log memory is full.
- -Modified to ensure logging session does not start if log memory is close to full.
- -Fixed a bug where a net that contained multiple Warning Icons that were set to output at different percentages of memory full did not work correctly. Only the Warning icon with the lowest percentage setting would assert its output.
- -Added support for recovery if a logger password is lost.
- -Added support for circular (backwards) net connections to the Alternate Rate input on the Sample Rate Clock Icon
- -Fixed a possible case where a failed FTP would not timeout properly and could cause FTP operation to hang.

LOGIC BEACH INCORPORATED