



LOGIC BEACH, Inc.

Instruments designed with the User in mind

SOFTWARE RELEASE NOTES

PRODUCT: INTELLILOGGER FIRMWARE VER 1.26.1.1

RELEASE DATE: 8-12-2025

RELEASE SPECIFIC NOTES:

IntelliLogger instrument firmware update. Install into target IntelliLogger using the Reflash Firmware command within HyperWare-II™ Logger menu.

HYPERWARE II COMPATIBILITY:

HyperWare-II™ version 1.26.2.3

MODIFICATIONS CONTAINED IN THIS RELEASE:

- FTP function modifications to better handle irregular FTP Server shutdowns
- Fixes to Modbus Client function for improved Server Name resolution
- Improved Diagnostic Log operation to allow for messages to be logged during power on boot.
- Window Comparator function change to match text shown in the HyperWare-II™ Window Comparator configuration dialog
- Implemented improved resolution mathematical calculations to avoid GPDI frequency errors when input frequency is extremely close to an integer frequency.
- Set a non-zero minimum GPDI frequency
- Improvement to key press for improved user interface